



# ASPEN Control Board & Wiring Diagram



**Wiring Option 1**  
(User supplied potentiometer)



**Wiring Option 2**  
(User supplied speed input voltage)

**Note** – Aspen recommends the use of a 10 amp inline fuse with all compressor installations. Littelfuse # 0312010 or equivalent.

